











NUOVA POMPA ACQUA
NOUVELLE POMPE À EAU

PA1560

NEW WATER PUMP
NEUE WASSERPUMPE

| | | | | |
|---|--|---|---|---|
|  |  |  |  |  |
| <p>29480 29483 22650 22650</p> | <p>HONDA Accord 2.0i-VTEC 16V HONDA Accord Tourer 2.0i-VTEC 16V HONDA CR-V 2.0i-VTEC 16V HONDA CR-V 2.0i-VTEC Auto 16V</p> | <p>P P P P</p> | <p>R20A3 R20A3 R20A2 R20A2</p> | <p>2008/05> 2008/05> 2006/12> 2006/12></p> |
| <p>OEM #</p> | |   | | |
| <p>19200R1PU01, 19200RZP003, 19200RZP013</p> | | | | |
| <p>DATI LOGISTICI / LOGISTIQUE PARAMÈTRE / LOGISTIC PARAMETERS / LOGISTISCHE DATEN</p> | | | | |
|  ABCD1234 |  |  | | |
| <p>8019738122153</p> | <p>mm 130x110x185</p> | <p>0,75 Kg</p> | | |



TecDoc
INSIDE

PREMIUM WATER PUMPS



INDUSTRIE SALERI ITALO

WWW.SALERI.IT

21/01/2015